

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

MICHAEL O. LEAVITT Governor

OLENE S. WALKER Lieutenant Governor

Representatives Present During the Inspection			
OGM	Joe Helfrich Reclamation Specialist III		
Company	Johnny Pappas Sr. Environmental Engineer		

Inspection Report

Permit Number:	C0070004		
Inspection Type:	COMPLETE		
Inspection Date:	Wednesday, September 10, 2003		
Start Date/Time:	9/10/2003 9:00:00 AM		
End Date/Time:	9/10/2003 4:00:00 PM		
Last Inspection:	Wednesday, August 13, 2003		

Inspector: Joe Helfrich, Reclamation Specialist III

Weather: rainy 55

Accepted by: dhaddock 9/17/2003

Permitee:	CASTLE GATE	HOLDING	CC
Operator:	CASTLE GATE	HOLDING	CO

Site: CASTLE GATE MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	7,619.00
Total Disturbed	63.00
Phase I	29.20
Phase II	18.20
Phase III	

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State Surface County Loadout ✓ Fee ✓ Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The purpose of this site visit was to conduct a complete inspection of the Castle Gate facility. Steve Fluke attended to facilitate the joint Hydro/Inspector visit.

Inspector's Signature:

Date

Monday, September 15, 2003

Joe Helfrich, Reclamation Specialist III

Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070004 Inspection Type: COMPLETE

Inspection Date: Wednesday, September 10, 2003

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		~	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading		✓		
13.	Revegetation	✓		✓	
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.	a Roads: Construction, Maintenance, Surfacing	✓			
16.	o Roads: Drainage Controls	✓			
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check		✓		
20.	Air Quality Permit		~		
21.	Bonding and Insurance	✓		✓	
22.	Other				

Permit Number: C0070004 Inspection Type: COMPLETE

Inspection Date: Wednesday, September 10, 2003

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The permit was renewed December 24, 1999. There are no amendments pending.

2. Signs and Markers

Signs containing the required information were posted at access points to the facilities.

3. Topsoil

The soil media used in reclamation of the #1 Adit was mostly in-place pre-law material containing some refuse. The first season vegetation establishment in the small refuse area is as good as or better than the other soil media areas.

4.a Hydrologic Balance: Diversions

The sediment control structures were in good repair and were functioning properly at the Hardscrabble, Sowbelly, and #1 adit reclaimed sites.

4.c Hydrologic Balance: Other Sediment Control Measures

Surface roughening, vegetation, diversions, and water bars are the sediment controls for the Hardscrabble, Sowbelly, and #1 adit reclaimed sites. The vegetation at Sowbelly and Hardscrabble has been evaluated and approved for phase II bond release. The sediment control measures were functioning adequately at the time of this inspection.

4.d Hydrologic Balance: Water Monitoring

The third quarter 2002 monitoring data (entered electronically) was reviewed by the undersigned. Hard copies of the data for the adit pond discharge were reviewed. Sites B11, 12, 28, and 45 were reported as dry.

$SITE \sqcup LOCATION \sqcup FREQUENCY \sqcup DATE \ SAMPLED$
B12□Hardscrabble Upper□Quarterly□Dry, 5/28/2003
B11 ☐ Hardscrabble Lower ☐ Quarterly ☐ Dry, 5/28/2003
B28□Sowbelly Upper□Quarterly□Dry, 6/03/2003
B45□Sowbelly Lower□Quarterly□Dry, 6/03/2003

13. Revegetation

At the #1 Adit, Fourwing saltbush, Western wheatgrass, and Blueleaf aster are well established. The vegetation at the Hardscrabble and Sowbelly sites is doing well in spite of several years of low precipitation.

Permit Number: C0070004 Inspection Type: COMPLETE

Inspection Date: Wednesday, September 10, 2003

Page 4 of 4

18. Support Facilities, Utility Installations

The power lines and poles from the #1 adit to Hardscrabble and Sowbelly have been removed. The cable is being wound on spools and the poles removed by helicopter. Minor clean up needs to be completed.

21. Bonding and Insurance

The surety bond is currently set at \$601,333.00 and the Certificate of Insurance is current through June 30, 2004.